

GREG BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection: OGM Pete Hess

Inspection Report

Permit Number:	C0070022
Inspection Type:	PARTIAL
Inspection Date:	Monday, October 24, 2011
Start Date/Time:	10/24/2011 8:53:00 AM
End Date/Time:	10/24/2011 1:15:00 PM
Last Inspection:	Monday, September 26, 2011

Inspector: Pete Hess.

Weather: Clear; cooler. 40-60's F. InspectionID Report Number: 2902

Types of Operations

Accepted by: jhelfric 11/1/2011

Permitee: SAVAGE SERVICES CORP Operator: SAVAGE SERVICES CORP Site: SAVAGE COAL TERMINAL

Address: 6340 S 3000 E STE 600, SALT LAKE CITY UT 84121

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

153.46	Total Permitted			
132.50	Total Disturbed			
	Phase I			
	Phase II			
	Phase III			

Mineral Ownership

✓ Other

Federal ✓ Underground State ✓ Surface County ✓ Loadout Fee Processing Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Mr. Vic Fausett represented Savage Services Corp. during today's inspection.

Inspector's Signature:

Pete Hess,

Inspector ID Number: 46

Date

Monday, Octol

OIL, GAS & MINING

Permit Number: C0070022 Inspection Type: PARTIAL

Inspection Date: Monday, October 24, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓			
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓		~	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	V		V	
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing				
16.t	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070022 Inspection Type: PARTIAL

Inspection Date: Monday, October 24, 2011

Page 3 of 3

4.a Hydrologic Balance: Diversions

The culvert inlet identified as C-2 (18 inch CMP) on Plate 7-2 was blocked. It was cleaned during the course of today's inspection.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The Permittee recently completed the cleanout of slurry cell #3; the material has been stored on the east side of cell 1 to dry.

4.d Hydrologic Balance: Water Monitoring

Second Quarter 2011 surface and ground water monitoring data has been uploaded into the DOGM permanent data base.

7. Coal Mine Waste, Refuse Piles, Impoundments

The Permittee has bladed the ditch identified as CD-13 on Plate 7-2.